

DE/0000

South District-Artasia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Black River Management	API Number 30-015-45442
Property Name Faulk SWD	Well No. 7

1. Surface Location

U/L	Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
	P	32	22S	28E	161	S	515	E	Eddy

Well Status

YES	TA'D WELL	YES	SHUT-IN	INJ	INJECTOR	OIL	PRODUCER	GAS	DATE
	NO		NO		SWD				7/31/2023

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0		0	2730
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 _____ WTR _____ GAS _____ Type of Fluid _____ Injected for _____ Water flood if _____ applies
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod csg. Slight fluid

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness:	[Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 250737

CONDITIONS

Operator: San Mateo Black River Water Management Compan 5400 LBJ Freeway Dallas, TX 75240	OGRID: 371287
	Action Number: 250737
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/26/2024