

Document

South District-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Extex	API Number 30-025-31601
Property Name Barnes 20	Well No. #1

2. Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County
	20	9S	35E	766	N	2201	W	Lea


Well Status

YES	TA'D WELL	YES	SHUT-IN	INJ	INJECTOR	OIL	PRODUCER	GAS	DATE
	(NO)		(NO)		(SWD)				07-29-23

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	20
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2 ☐ WTR ☒ GAS ☐ Type of Field Injected for Waterflood if applies
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION	
Printed name:	Entered into RBDMS	
Title:	Re-test	
E-mail Address:		
Date:	Phone:	
	Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 250459

CONDITIONS

Operator: Extex Operating Company 1616 S. Voss Road Houston, TX 77057	OGRID: 330423
	Action Number: 250459
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/26/2024