District *I*
1625 N. French Dr., Hobbs, NM 88240
Phone: *(575) 393-6161 Fax: (575) 393-0720*

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name	API Number
Mack Energy Corporation	30-025-36370

Property Name	Well No.
Lea KG State	9

₇ Surface Location

UL- Lot	Section	Township	Range		Feet from	N/S Line	Feet from	E/W Line	County
I	35	17S	33E		1395	South	1255	East	Lea, NM

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES	NO	YES	NO	INJ	SWD	OIL	GAS	

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradehead flowed water. check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod-Tubing	(E) Tubing
Pressure					
Flow Characteristics					
Puff	Y/ N	Y/ N	Y/ N	Y/ N	C02___
Steady Flow	Y / N	Y / N	Y/ N	Y/N	WTR___
Surges	Y/ N	Y / N	Y / N	Y / N	GAS___
Down to nothing	Y / N	Y / N	Y / N	Y/N	Type of fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	injected for Waterflood
Water	Y / N	Y / N	Y / N	Y/ N	if applies

Remarks:

Plugged

Signature:	OIL CONSERVATION DIVISION
Printed Name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	Phone: 575-748-1288	
	Witness:	

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
MACK ENERGY CORP P.O. Box 960 Artesia, NM 882110960	13837

	Action Number:
	250166

	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/26/2024