

District 2 Artesia

District 2 Artesia

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

**BRADENHEAD TEST REPORT**

Operator Name <b>Bxp Operating</b>	API Number <b>30-015-34212</b>
Property Name <b>East Shugart Delaware unit</b>	Well No. <b>#25</b>

1. Surface Location

UL - Lot <b>A</b>	Section <b>24</b>	Township <b>18S</b>	Range <b>31E</b>	Feet from <b>250</b>	N/S Line <b>N</b>	Feet From <b>1125</b>	E/W Line <b>E</b>	County <b>Eddy</b>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/>	SWD	OIL PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE <b>5-5-2023</b>
--	--	--	-----	---	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	<b>0</b>			<b>0</b>	<b>1200</b>
<u>Flow Characteristics</u>					
Puff	Y / <input checked="" type="radio"/> N	Y / N	Y / N	<input checked="" type="radio"/> Y / N	CO2 <input type="checkbox"/>
Steady Flow	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y / N	Y / N	Y / N	<input checked="" type="radio"/> Y / N	Type of fluid injected for Waterflood if applies
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	
Water	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Y / <input checked="" type="radio"/> N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Production csg has small puff, down to nothing

Signature: <b>Ryan Martin</b>	OIL CONSERVATION DIVISION
Printed name: <b>Ryan Martin</b>	Entered into RBDMS
Title: <b>AGENT</b>	Re-test
E-mail Address: <b>Mymerch@Penrocoil.Com</b>	
Date: <b>5-5-23</b>	Phone: <b>575-492-1236</b>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

BL

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 257303

CONDITIONS

Operator: BXP Operating, LLC 11757 KATY FREEWAY HOUSTON, TX 77079	OGRID: 329487
	Action Number: 257303
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024