DODGOODOK

District 2 Artesia

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office



			TEST REPORT					
Bxp Operating				30-015-34409				
Park way Delware Drut				# 707				
¹ Surface Location								
	98 29E	Feet fr \980		Free From E/W Line	Eday			
Well Status								
YES TA'D WELL	YES SHUT-IN	NO (INJECT	SWD OIL	PRODUCER GAS 3/	24 2023			
OBSERVED DATA								
	(A)Surface	(B)Interm(1)	(Olnterm(2)	(D)Prod Csng	(E)Tubing			
Pressure	0			Õ	1200			
Flow Characteristics								
Puff	Y / (P)	Y/N	YIN	YIN	CO2 WTR			
Steady Flow	Y/	N/N	¥ \Y / N	Y / (N)	GAS _			
Surges	Y/N	Y/W	* 1 N	Y / (N)	Type of Fluid			
Down to nothing	(Y) N	5 Y/N	Y-V N	(Y)/ N	Jajecoud for Waterflood if			
Gas or Oil Water	Y / (N) Y / (N)	Y/N Y/N	Y /\N Y / N	Y / (N)	a pyrács			
vvate:		171	. 1					
Remarks - Please state for each	ch string (A,B,C,D,E) per	tinent information regarding	bleed down or continuous	build up if applies.				
	•							
					•			
					`			
//	1 ,							
Signature: Rm Wat				OIL CONSERVATION DIVISION				
Printed name: Ryan Manain			E	Entered into RBDMS				
Title: Agent				Re-test				

INSTRUCTIONS ON BACK OF THIS FORM

Phone: 575-492-1236

Witness:



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 257298

CONDITIONS

Operator:	OGRID:
BXP Operating, LLC	329487
11757 KATY FREEWAY	Action Number:
HOUSTON, TX 77079	257298
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024