District 2 Artesia

State of New Mexico Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OXY USA WTP LP							30-015-44154			
Property Name TURKEY TRACK 9 10 STATE						Well No. 23H				
					7. Surface Locat	ion				
UL-Lot P	Section 8	Township 19S	Range 29E		Feet from 1195	N/S	S Line	Feet From 220	E/W Line E	County EDDY
					Well Statu	S				
TA'D	WELL N	O YES	SHUT-IN	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	08-1	DATE 8-23

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing	
Pressure	0	0		650	300	
Flow Characteristics	(A-10-14-)					
Puff	Y/ N	Y/ N	Y / N	Y / N	CO2	
Steady Flow	Y/N	Y /N	Y / N	Y / N	WTR_	
Surges	Y/N	Y/N	Y / N	Y / N	GAS	
Down to nothing	Y/ N	Y/ N	Y / N	Y / N	Injected for Waterflood if	
Gas or Oil	Y/N	Y/N	Y / N	Y / N	applies.	
Water	Y/N	Y /N	Y / N	Y / N	7	

Remarks - Please state for each string (A,B,C,D,E) pertinent information reg-	garding bleed down or continuous build up if applies.	
A. NO RECORDABLE PRESSURE B. NO RECORDABLE PRESSURE		

Signature:		OIL CONSERVATION DIVISION
Printed name: MOISES	JAQUEZ	Entered into RBDMS
Title: WORKOVER A	AND COMPLETIONS SPECIALIST	Re-test
E-mail Address: MOISES	S_JAQUEZ@OXY.COM	10001
Date: 08-18-23	Phone: 575-408-6137	
	Witness: FABIAN HERNANDEZ (HOT OILER OP)	432-888-0211

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 254721

CONDITIONS

Operator:	OGRID:
OXY USA WTP LIMITED PARTNERSHIP	192463
P.O. Box 4294	Action Number:
Houston, TX 772104294	254721
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024