DOCUMENT

District 2 Artesia

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office



BRADENHEAD TEST REPORT Operator Name 30-025-00446 Well No. Property Name 1. Surface Location Section Township Range Feet from N/S Line Feet From E/W Line County O3(060) 2080 Well Status INJECTOR TA'D WELL SHUT-IN PRODUCER YES NO SWD OIL GAS **OBSERVED DATA** (A)Surface (B)Interm(1) (C)Interm(2) (D)Prod Csng (E)Tubing Pressure Flow Characteristics CO₂ Y /('N) Puff Y/N Y / N Y / (N) WTR ^ Y / (N) Steady Flow Y / N X/N Y //N GAS Y / (N) Y / (N) Surges YV N Type of Fluid Down to nothing (Y) / N Jajected for (Y) / N Y/N Y'/ N Waterflood if Gas or Oil Y/N Y/W Y/N Y / N a ondes Y/N Y/N Water Y/N Y / N Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. Signature: OIL CONSERVATION DIVISION yan Martin Entered into RBDMS Printed name: Re-test Title: E-mail Address: 575-492.1236 Date: * Phone: Witness:

INSTRUCTIONS ON BACK OF THIS FORM

GR

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 257315

CONDITIONS

Operator:	OGRID:
BXP Operating, LLC	329487
	Action Number:
HOUSTON, TX 77079	257315
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024