

District I
1635 N Fresno Dr., Hobbs, NM 88240
Phone: (575) 392-6151 Fax: (575) 391-6720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Rover Operating LLC	API Number 30-025-00535
Property Name Malmar	Well No. 108

Surface Location									
UL Loc H	Section 13	Township 17S	Range 32E	Feet from 1980	NS Line NL	Feet from 660	EAV Line EL	County Lea	

Well Status									
TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	☒ INJ	SWD	OIL	PRODUCER GAS	DATE 8-15-23	

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	N/A	N/A	0	2100
Flow Characteristics					
Puff	☒ Y ☐ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	CO2 WTR ☒ GAS ☐ Type of fluid Subjected for Water/Oil/Gas Analysis
Steady Flow	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	
Surges	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	
Down to nothing	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	
Gas or Oil	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	
Water	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	☐ Y ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Kirk Farves	Entered into RBDMS
Title: Production Foreman	Re-test GR
E-mail Address: KFarves@RoverPetro.com	
Date: 8-15-23	
Phone: 575-513-3198	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 254367

CONDITIONS

Operator: ROVER OPERATING, LLC 318 West Adams Street Chicago, IL 60606	OGRID: 371484
	Action Number: 254367
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024