DOORSON

## District 2 Artesia

# State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT													
Bx P Operator Name								30-025-01454					
Caprock majorar unit # 20 Well No.													
'. Surface Location													
UL - Lot	Section	Townsh	Range 33 E			Feet from	N/S	S Line	Feet From 1980	Ñ	E/W Line	County LEA	
Well Status													
YES TA'D	WELL (N	9 Y	SHUT-IN ES	NO	(ND	INJECTOR	swD	OIL	PRODUCER (	GAS	7-1	DATE 8 - 2023	

# OBSERVED DATA

(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
0			0	1800
Y / 🚫	Y/N	Y/N	Y / 🕅	CO2
Y / (N)	Y/N	Y/N	Y / 🔊	WTR /
Y /(N)	YXN	VIN	Y / (N)	TOTH OF FINA
8)/ N	7 4 Y'/ N	YXN	NY	Jajected for Waterflood If
Y /(N)	· Y/N	Y/N	Y/N	app6cs
Y / (N)	Y/N	Y/N	Y / 🕅	
	Y / (N)	Y/(S) Y/N Y/(S) Y/N Y/(N) Y/N Y/(N) Y/N Y/(N) Y/N Y/(N) Y/N	Y/N	Y/® Y/N Y/N Y/®  Y/® Y/N Y/N Y/®

Remarks - Please state for each string (A,B,C,D,E) pertin	ent information regarding bleed down or continuous build up if applies.	
		*
]	,	
· ·		

Signature: Rash	OIL CONSERVATION DIVISION				
Printed name: O Ryan Martin	Entered into RBDMS /				
Title: AGENT	Re-test /				
E-mail Address: Mymerch @ Penrocoll. Com					
Dale: 7/19/23 Phone: 575-492-1236	·				
Witness:					

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 258552

### **CONDITIONS**

Operator:	OGRID:
BXP Operating, LLC	329487
11757 KATY FREEWAY	Action Number:
HOUSTON, TX 77079	258552
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

## CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024