District I 1625 N. French Dr., Hobbs, NM 88240 Phone (575) 393-6161. Fax. (575) 393-0720.

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name								API Number			
Seely Oil Company						30-02	30-025-01635				
Property Name								Well No.			
EK Queen Unit								#026			
³ Surface Location											
UL - Lot	Section	Township	Range			Feet from	N/S	Line	Feet From	E/W Line	County
K	24	185	33E			2310		S	2310	W	Lea
Well Status											
(YES) TA'D	WELL N	o (YES	SHUT-IN	NO	(INJ)	INJECTOR	SWD	OIL	PRODUCER GA	is 7-	DATE 25-23

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			100	100 00
Flow Characteristics					
Puff	YIN	Y/N	Y/N	(V)	CO2
Steady Flow	Y/N	Y/N	Y / N	A. CM	WIR
Surges	Y (N)	Y/N	Y/N	Y/W	Type of Fluid
Down to nothing	Co	Y / N	Y/N	(Y)N	Injected for Waterflood if
Gas or Oil	Y A	Y/N	Y/N	Y (N)	applies
Water	Y/N	Y / N	Y / N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. Called Mike - Prod. CSJ blew to Zero IN	min.

Signature. Mike Fra	ne s	OIL CONSERVAT	OIL CONSERVATION DIVISION		
Printed name:		Entered into RBDMS	10		
Title		Re-test			
E-mail Address:					
Date 7-25-23	Phone.				
	Witness.	/			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 255326

CONDITIONS

Operator:	OGRID:
SEELY OIL CO	20497
815 W 10th Street	Action Number:
Ft. Worth, TX 76102	255326
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024