

District I  
1625 N. French Dr., Hobbs, NM 88240  
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

## BRADENHEAD TEST REPORT

Operator Name Seely Oil Company		API Number 30-025-02350	
Property Name EK Queen Unit		Well No. #067	

## Surface Location

UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
2	19	18S	34E		1980	N	610	W	Lea

## Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR SWD	PRODUCER OIL	GAS	DATE 7-25-23
------------------	----------------	-----------------	-----------------	-----	-----------------

## OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	—	—	0	2000
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR —
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	Type of Fluid
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	Is ejected for
Water	Y / (N)	Y / N	Y / N	Y / (N)	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Mike Frasier</i>		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title		Re-test	
E-mail Address:			
Date: 7-25-23	Phone:		
	Witness		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 255294

CONDITIONS

Operator: SEELY OIL CO 815 W 10th Street Ft. Worth, TX 76102	OGRID: 20497
	Action Number: 255294
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024