

BROOKS

District 2 Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Bxp	API Number 30-025-11443
Property Name Langlie Jal unit	Well No. # 44

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
E	04	28S	37E	2310	N	990	N	LEA

Well Status

YES	TA'D WELL	YES	SHUT-IN	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
	(NO)		(NO)	(INJ)					7-18-2023

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	575
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ☒
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS ☐
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	Type of fluid injected for waterflood if applies
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Ryan Martin	OIL CONSERVATION DIVISION
Printed name: Ryan Martin	Entered into RBDMS
Title: AGENT	Re-test
E-mail Address: Mymerch@Penrockoil.com	
Date: 7/18/23	Phone: 575-492-1236
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

14

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 258560

CONDITIONS

Operator: BXP Operating, LLC 11757 KATY FREEWAY HOUSTON, TX 77079	OGRID: 329487
	Action Number: 258560
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024