

District 2 Artesia

District 2 Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Bxp	API Number 30-025-11506
Property Name Langlie Jal unit	Well No. # 72

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
C	08	25S	37E	660	N	2310	N	LEA

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE
NO	NO	INJ				

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	550
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 <input checked="" type="checkbox"/> WTR <input checked="" type="checkbox"/> GAS <input type="checkbox"/> Type of fluid injected for waterflood if applies
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Ryan Martin	OIL CONSERVATION DIVISION
Printed name: Ryan Martin	Entered into RBDMS
Title: AGENT	Re-test
E-mail Address: Mymarch@Penroc.oil.com	
Date: 7/18/23	
Phone: 575-492-1236	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

32

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 258572

CONDITIONS

Operator: BXP Operating, LLC 11757 KATY FREEWAY HOUSTON, TX 77079	OGRID: 329487
	Action Number: 258572
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024