

D8882222

District 2 Artesia

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

## BRADENHEAD TEST REPORT

Operator Name <b>Bxp</b>	API Number <b>30-025-23186</b>
Property Name <b>Langlie Mattix Queen Unit</b>	Well No. <b>#22</b>

## 1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
<b>N</b>	<b>15</b>	<b>25S</b>	<b>37E</b>	<b>668</b>	<b>S</b>	<b>1633</b>	<b>W</b>	<b>LEA</b>

## Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES NO	YES NO	INJ SWD	OIL GAS	

## OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	200
<u>Flow Characteristics</u>					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2 _____ WTR <input checked="" type="checkbox"/> GAS _____ Type of Fluid Injected for Waterflood if applies
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	
Surges	Y / (N)	Y / N	Y / N	Y / (N)	
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <b>Ryan Martin</b>	OIL CONSERVATION DIVISION
Printed name: <b>Ryan Martin</b>	Entered into RBDMS
Title: <b>AGENT</b>	Re-test
E-mail Address: <b>Mymerch@Penrocoil.com</b>	
Date:	Phone: <b>575-492-1236</b>
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 258532

CONDITIONS

Operator: BXP Operating, LLC 11757 KATY FREEWAY HOUSTON, TX 77079	OGRID: 329487
	Action Number: 258532
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024