

District I
1525 N. French Dr., Hobbs, NM 88240
Phone: (575) 392-6151 Fax: (575) 395-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name OWC		API Number 30-025-27684	
Property Name Toplat ASQ ST.		Well No. #1	

1. Surface Location									
UL - Lot H	Section 35	Township 23E	Range 33E	Feet from 1580	N/S Line N	Feet from 66E	E/W Line E	County LEA	

Well Status							DATE
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL PRODUCER GAS	7-20-23

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	1213
Flow Characteristics					
Puff	Y N	Y / N	Y / N	Y N	C02
Steady Flow	Y N	Y / N	Y / N	Y N	WTR
Surges	Y N	Y / N	Y / N	Y N	GAS
Down to nothing	Y N	Y / N	Y / N	Y N	Type of fluid
Gas or Oil	Y N	Y / N	Y / N	Y N	Is/used for
Water	Y N	Y / N	Y / N	Y N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:	GR	
Witness:	Steve Rolando		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 253149

CONDITIONS

Operator: OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID: 308339
	Action Number: 253149
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	11/27/2024