

000000X

South District-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name LH Operating	API Number 30-015-05185
Property Name Turner B	Well No. 7

Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County
0	17	17S	31E	660	FSL	1980	FEL	Edgy

Well Status

YES	TA'D WELL	YES	SHUT-IN	INJECTOR	SWD	PRODUCER	GAS	DATE
	NO		NO	IND		OIL		6-29-23

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	740
Flow Characteristics					CO2
Puff	Y / N	Y / N	Y / N	Y / N	WTR ✓
Steady Flow	Y / N	Y / N	Y / N	Y / N	GAS
Surges	Y / N	Y / N	Y / N	Y / N	Type of fluid
Down to nothing	0 / N	Y / N	Y / N	0 / N	Injected for
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Waterhead if
Water	Y / N	Y / N	Y / N	Y / N	applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT - OK

Signature: Mike Burton	OIL CONSERVATION DIVISION
Printed name: Mike Burton	Entered into RBDMS
Title:	Re-test
E-mail Address: M.k @ LH Operating .com	
Date: 6-29-23	Phone: 575-499-5306
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 267490

CONDITIONS

Operator: LH Operating, LLC 3730 Kirby Drive Houston, TX 77098	OGRID: 329319
	Action Number: 267490
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/2/2024