

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name

LD Operating
Turner B

API Number

30-015-20109

Well No.

79

Property Name

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County
K	20	175	31E	2050	S	1980	W	Eddy

Surface Location

Well Status

TA'D WELL	SHUT-IN	INJECTOR	SWD	PRODUCER	GAS	DATE
YES	NO	NO INJ	SWD	OIL	GAS	7/1/2024

OBSERVED DATA

	(A)Surface	(B)Interim(1)	(C)Interim(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	/	0	800
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT: 06

Signature:	<i>Mike Burton</i>	
Printed name:	Mike Burton	
Title:		
E-mail Address:		
Date: 7-1-24	Phone:	
	Witness:	<i>Bob Barber</i>
OIL CONSERVATION DIVISION		
Entered into RBDMS		
Re-test		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 363185

CONDITIONS

Operator: LH Operating, LLC 3730 Kirby Drive Houston, TX 77098	OGRID: 329319
	Action Number: 363185
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/2/2024