

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name CHI Operating, Inc.	API Number 30-015-35085
Property Name Benson Delaware Unit	Well No. 10

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
H	11	19S	30E	2200	FNL	330	FEL	EDDY

Well Status

TA'D WELL YES NO	SHUT-IN YES NO	INJECTOR INJ	PRODUCER OIL GAS	DATE 7-12-23
----------------------------	--------------------------	------------------------	----------------------------	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	640
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 <input type="checkbox"/>
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR <input checked="" type="checkbox"/>
Surges	Y / N	Y / N	Y / N	Y / N	GAS <input type="checkbox"/>
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

Signature: J. C. D. Jr.	OIL CONSERVATION DIVISION
Printed name: Thomas Duran Sr.	Entered into RBDMS
Title: Prod. op.	Re-test
E-mail Address: atom17@me.com	
Date: 7-12-23	Phone: 575-706-5028
Witness: Robert	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 267761

CONDITIONS

Operator: CHI OPERATING INC P.O. Box 1799 Midland, TX 79702	OGRID: 4378
	Action Number: 267761
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	11/4/2024