

OIL CONSERVATION DIVISION		Entered into RBDMS		Re-test	
Signature:		Printed name:		Title:	
		Reggie House		Title:	
E-mail Address:		Phone:		Witness:	
Date: 9-8-23					

[illegible]

Pressure	Flow Characteristics	Puff	Steady Flow	Surges	Down to nothing	Gas or Oil	Water
(A) Surf-Interm		Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)
(B) Interm-Interm(2)		Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)
(C) Interm-Prod		Y / N	Y / N	Y / N	Y / N	Y / N	Y / N
(D) Prod Csg		Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)
(E) Tubing		Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)	Y / (N)

It Bradenhead flowed water, check all of the sdescriptions that apply:

OBSERVED DATA

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TAD Well	SHUT-IN	INJ	OIL	GAS	DATE
Yes	Yes	Yes	Yes	Yes	5-8-23
No	No	No	No	No	

Well Status

UL - Lot	Section	3	Township	22S	Range	31E	Pct From	1500	N/S Line	N	Pct From	S41	B/W Line	E	County	EDDY
----------	---------	---	----------	-----	-------	-----	----------	------	----------	---	----------	-----	----------	---	--------	------

Surface Location

Operator Name	OXY USA INC	API Number	30-015-38254
Property Name	LOST TANK 3 FEDERAL		
Well No.	25		

BRADENHEAD TEST REPORT

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

District 2
811 S. 1st Street, Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 267277

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 267277
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/2/2024