

OIL CONSERVATION DIVISION	Signature: <i>[Signature]</i>	Printed name: Reggie House	Title:	E-mail Address:	Date: 9-8-23	Phone:	Witness:
Entered into RBDMS							
Re-test							

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

[illegible]

If Bradenhead flowed water, check all of the descriptions that apply:

OBSERVED DATA

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Yes	NO	Yes	NO	Yes	NO	DATE
T&D Well	SHUT-IN	INJECTOR	SWD	OIL	GAS	9-8-2023

Well Status

UL- Lot	Section	21S	Range	2630	S	2630	W	EDDY
				Feet From	N/S Line	Feet From	E/W Line	County

Surface Location

Operator Name	OXY USA INC	API Number	30-015-40890
Property Name	LOST TANK 35 STATE SWD		
Well No.	1		

BRADENHEAD TEST REPORT

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

District 7
811 S. 1st Street, Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 267275

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 267275
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/2/2024