

District I
1635 N French Dr., Hobbs, NM 88240
Phone: (575) 392-6151 Fax: (575) 393-6720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Rover Operating	API Number 30-015-10328
Property Name West Artesia Greyburg Unit	Well No. # 006

Surface Location									
UL - Lot G	Section 08	Township 18S	Range 28E	Feet from 2310	N/S Line EVL	Feet From 1980	E/W Line EEL	County EAAY	

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS
									DATE 9/4/2024

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0			0	930
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Isolated for
Water	Y/N	Y/N	Y/N	Y/N	Water/Oil/Gas

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK
Step rate test Approved 9/9/2014 to 1104^{hr}

Signature: [Signature]	OIL CONSERVATION DIVISION
Printed name: Kirk Farves	Entered into RBDMS
Title: Foreman	Re-test
E-mail Address: KFarves@RoverPetro.com	
Date: 9-4-24	
Phone: 575-513-3198	
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 407233

CONDITIONS

Operator: ROVER OPERATING, LLC 318 West Adams Street Chicago, IL 60606	OGRID: 371484
	Action Number: 407233
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/3/2024