Received by OCD: 11/26/2024 1:00:38 PM

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT							
Apache Comporation				30.015-22914			
Emoire ABO Unit					Well No.		
	² Surface Location						
UL-Lot Section Township 185	27E	Feet from 1310	N/S Line	Feet From 590	E/W Line County		
Well Status							
TA'D WELL NO YES	SHUT-IN NO	INJECTOR INJ	SWD OIL	PRODUCER GA	s 11/20/2024		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	/	4		NIA
Flow Characteristics	6				
Puff	Y / (N)	Y/N	Y/N/	Y /(N)	CO2
Steady Flow	Y / (N)	Y/N/	Y/X	Y / 🚫	WTR GAS
Surges	Y/N	Y/N	Y // N	Y / (N)	T) pe of Finis
Down to nothing	(TY N	Y //N	y/ N	(Y) N	Injected for Waterflund if
Gas or Oil	YIN	y/ N	/Y / N	Y / N	applies
Water	Y / NS	/Y / N	/ Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. TA Status BHT.OK

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
	Witness: Standard during	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 406776

CONDITIONS

Operator:	OGRID:
APACHE CORPORATION	873
303 Veterans Airpark Ln	Action Number:
Midland, TX 79705	406776
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
kfortner	None	12/3/2024