

District II – Artesia811 S. 1st Street, Artesia, NM 88210

Phone: (575) 748-1283 - Fax: (575)-748-9720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name El Paso Natural Gas Company		API Number 30-015-24053	
Property Name W.I. Federal		Well No. #21	

7. Surface Location

UL - Lot	Section 34	Township 25S	Range 24E	Feet from 2,150	N/S Line South	Feet From 2,150	E/W Line West	County Eddy
----------	---------------	-----------------	--------------	--------------------	-------------------	--------------------	------------------	----------------

Well Status

TA'D Well YES <input checked="" type="radio"/> NO	SHUT-IN YES <input checked="" type="radio"/> NO	INJECTOR <input checked="" type="radio"/> IN <input type="radio"/> SWD	PRODUCER OIL <input type="radio"/> GAS	DATE 11-6-23
--	--	---	---	-----------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	10	XXXXXXXXXXXX	XXXXXXXXXXXX	10	1.355
Flow Characteristics					
Puff	<input checked="" type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	CO2 <input type="checkbox"/>
Steady Flow	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	WTR <input type="checkbox"/>
Surges	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	GAS <input checked="" type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input checked="" type="radio"/> Y <input type="radio"/> N	If applicable type
Gas or Oil	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	fluid injected for
Water	<input type="radio"/> Y <input checked="" type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input type="radio"/> N	<input type="radio"/> Y <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Gas Storage Injection/Withdrawal Well.

Signature: <i>Travis Moore</i>		OIL CONSERVATION DIVISION	
Printed name: Travis Moore		Entered RBDMS	
Title: Op's Supervisor		Re-test	
E-mail Address: travis_moore3@kindermorgan.com			
Date: 11-6-23	Phone: 575-234-5415		
Witness:			

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 296676

CONDITIONS

Operator: El Paso Natural Gas Company, L.L.C 1001 Louisiana Street Houston, TX 77002	OGRID: 7046
	Action Number: 296676
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/3/2024