

b666666

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Black River Water Management	API Number 30.015-44571
Property Name Malaga SWD	Well No. 5

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	NS Line	Feet From	E/W Line	County
2	12	24S	28E	1779	S	975	W	Eddy

Well Status

TA'D WELL	SHUT-IN	INJ	INJECTOR	OIL	PRODUCER	GAS	DATE
YES	YES	YES	YES	YES	YES	YES	7/8/2024
NO	NO	NO	SWD	SWD	SWD	SWD	

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	0	0	2500
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	X / N	Y / N	Y / N	Y / N	Type of Field
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Isjected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 366430

CONDITIONS

Operator: San Mateo Black River Water Management Compan 5400 LBJ Freeway Dallas, TX 75240	OGRID: 371287
	Action Number: 366430
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/3/2024