

District 2 Artesia

**State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office**

BRADENHEAD TEST REPORT

Operator Name OXY USA INC		API Number 30-015-44636	
Property Name CORRAL CANYON 36 25 FEDERAL COM			Well No. 26H

1. Surface Location

UL - Lot A	Section 1	Township 25S	Range 29E		Feet from 940	N/S Line N	Feet From 1213	E/W Line E	County EDDY
---------------	--------------	-----------------	--------------	--	------------------	---------------	-------------------	---------------	----------------

Well Status


TA'D WELL YES	<input checked="" type="checkbox"/> NO	SHUT-IN YES	<input checked="" type="checkbox"/> NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 09-05-23
------------------	----------------------------------------	----------------	----------------------------------------	-----	-----------------	-----	-----------------	------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Cspg	(E)Tubing
Pressure	0	0		780	250
Flow Characteristics					
Puff	<input checked="" type="checkbox"/> Y / N	<input checked="" type="checkbox"/> Y / N	Y / N	Y / N	CO2 ____ WTR ____ GAS ____ Type of Fluid Injected for Waterflood if applies
Steady Flow	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / N	
Surges	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / N	
Down to nothing	<input checked="" type="checkbox"/> Y / N	<input checked="" type="checkbox"/> Y / N	Y / N	Y / N	
Gas or Oil	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / N	
Water	Y / <input checked="" type="checkbox"/> N	Y / <input checked="" type="checkbox"/> N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. NO RECORDABLE PRESSURE
B. NO RECORDABLE PRESSURE

Signature: 	OIL CONSERVATION DIVISION	
Printed name: MOISES JAQUEZ	Entered into RBDMS	
Title: WORKOVER AND COMPLETIONS SPECIALIST	Re-test	
E-mail Address: MOISES_JAQUEZ@OXY.COM		
Date: 09-05-23	Phone: 575-408-6137	
	Witness: FABIAN HERNANDEZ (HOT OILER OP)	432-888-0211

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 279859

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 279859
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/3/2024