District 2 Artesia

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

				BKA	DENHEAD II	721 KG	PURI			
Operator Name OXY USA INC						30-015-44703				
Property Name CORRAL FLY 35 26 FED COM						Well No. 22H				
					^{7.} Surface Loca	tion				
UL - Lot D	Section 2	Township 25S	Range 29E		Feet from 694	N/S	Line N	Feet From 1278	E/W Line	County EDDY
					Well State	18				3-11
TA'D WELL YES		yes	SHUT-IN	NO	INJ SWD OIL		PRODUCER GAS	5.115		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0	0		655	290
Flow Characteristics					
Puff	Y/N	Y/ N	Y / N	Y / N	CO2
Steady Flow	Y/N	Y / N	Y / N	Y / N	WTR_
Surges	Y/N	Y / N	Y / N	Y / N	GAS
Down to nothing	YN	YN	Y/N	Y / N	Injected for
Gas or Oil	Y /N	Y / N	Y / N	Y / N	Waterflood if applies
Water	Y/N	Y / N	Y / N	Y / N	7

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

A. NO RECORDABLE PRESSURE

B. NO RECORDABLE PRESSURE

Signature:	ext here	OIL CONSERVATION DIVISION		
Printed name: MOISES	JAQUEZ	Entered into RBDMS		
Title: WORKOVER A	ND COMPLETIONS SPECIALIST	Re-test		
E-mail Address: MOISE	S_JAQUEZ@OXY.COM			
Date: 09-06-23	Phone: 575-408-6137			
	Witness: FABIAN HERNANDEZ (HOT OILER OP)	432-888-0211		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 279892

CONDITIONS

Operator:	OGRID:				
OXY USA INC	16696				
P.O. Box 4294	Action Number:				
Houston, TX 772104294	279892				
	Action Type:				
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)				

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/3/2024