

District 1
1623 N French Dr, Hobbs, NM 88240
Phone (505) 393-5161 Fax (505) 393-0220

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CROSS TIMBER ENERGY, LLC		API Number 30-025-23460
Property Name NORTH VACUUM ABO UNIT		Well No 135

Surface Location									
UL - Lot L	Section 11	Township 17S	Range 34E	Feet from 1980	N/S Line FSL	Feet From 860	E/W Line FWL	County LEA	

Well Status									
YES	NO	YES	NO	NO	INJECTOR	SWD	OIL	PRODUCER	GAS
									DATE 6-11-2024

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure					
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Isolated for
Water	Y/N	Y/N	Y/N	Y/N	Washed if
					apples

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

TBH / PRR leak FAIL - Well has not been repaired since 8-9-23 failure. Well is to be shut in ASAP.

should have been shut in 8-9-23

Signature 		OIL CONSERVATION DIVISION	
Printed name Anthony Barrios		Entered into RBDMS	
Title Lease Operator		Re-test	
E-mail Address anbarrios@cross-timber.com			
Date 6-11-2024	Phone 505-441-1624		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 383192

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 383192
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/3/2024