State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

PDADENUEAD TEST DEDODT

		RADENHEAD IES	SI REPUR	1					
Operator Name, API Number									
Morningstar Derating Central Vacuum Unit					Well No.				
		7. Surface Location	on						
UL - Lot Section Tow 2 36 17	S 34t	Feet from	N/S Line	Feet F		E/W Line	County LEA		
	CHUDIN	Well Status		PROPILIC	70	T	2.000		
TA'D Well YES NO	SHUT-IN YES NO	INJ S	*	PRODUCER OIL N / GAS		10-28-24			
OBSERVED DATA									
	(A)Surf-Interm	(B)Interm(1)	(C)Interm(2)	· · · · · · · · · · · · · · · · · · ·	(D)Prod C	sng	(E)Tubing		
Pressure	-12-	/		/	-0	_	-0-		
Flow Characteristics				/					
Puff	Y/09	Y / N /	Y /		Y/89		CO2		
Steady Flow	Y/0	Y / N	Y	N	1	100	WTR		
Surges	YIO	Y //N	X /	N	YIO		GAS		
Down to nothing	Ø N	y / N	Y /		Ø N		If applicable type		
Gas or Oil	Y / (S)	Y / N	/	/ Y / N			fluid injected for Waterflood		
Water	Y /(Y)	/ Y / N	Y /	N	YCN		Watermood		
If bradenhead flowed water, ch	heck all of the descriptions	that apply:							
CLEAR	FRESH	SALTY	SUL	FUR		BLACK			
Remarks: Please state for expenses of the st	ach string (A,B,C,D,E)		ding bleed dow	n or continu	uous build u	p if applies			
Signature:				OIL CONSERVATION DIVISION					
Printed name: KEVIN BENNETT				Entered into RBDMS					
Title:					Re-test				
E-mail Address:	· · · · · · · · · · · · · · · · · · ·								
Date: 10-28-2	My Phone:								
	Witness:								
							Call		

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 396630

CONDITIONS

Operator:	OGRID:		
MorningStar Operating LLC	330132		
400 W 7th St	Action Number:		
Fort Worth, TX 76102	396630		
	Action Type:		
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)		

CONDITIONS

Created By		Condition Date
kfortner	None	12/3/2024