District I 1625 N French Dr., Hobbs, NM 88240 Phone (575) 393-6161 Fax. (575) 393-0120

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT MORNINGSTAR OPERATING, LLC API Number 30-025-41154 Property Name Well No 256 CENTRAL VACUUM UNIT 1. Surface Location UL-Lor Section 36 Township 17S Rauge 34E Feet from 1480 NS Line FNL Feet From E/W Line FWL County LEA 1990 Well Status TA'D WELL SHUT-IN INJECTOR PRODUCER (MI) YES NO (NO/ 9-4-24 YES SWD GAS OBSERVED DATA (A)Surface (B)Interm(1) (Ointerm(2) (D)Prod Csng (E)Tubing Pressure G 1720 Flow Characteristics Puff Y/N CO2 VIN Y/N Steady Flow YIN WIR YIN YIN Surges Y/N GAS YIN The of Field Down to nothing (Y) N YYN YIN Internet for Gas or Oil Y / (N) Waterflood if YIN YIO Water YIN Y / N YIN Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

26		OIL CONSERVATION DIVISION	
Printed name Enrique	Carmone	Entered into RBDMS	1/1
Title Lease Operator		Re-test	
E-mail Address: Carmo	na Ochar Hs vcs.com		
Date: 9-4-24	Phone 682-404-3121		
	Wigness		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 396660

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	396660
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortn	er None	12/3/2024