

District I
1523 N. French Dr., Hobbs, NM 88240
Phone: (575) 397-6151 Fax: (575) 397-6720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOR	API Number 30-041-00087
Property Name Milnesand #36	Well No. #36

2. Surface Location

UL - Lot N	Section 18	Township 8S	Range 35E	Feet from	NS Line	Feet from	E/W Line	County Rosv.
----------------------	----------------------	-----------------------	---------------------	-----------	---------	-----------	----------	------------------------

Well Status

TA'D WELL NO	SHUT-IN NO	INJECTOR INJ	SWD	OIL	PRODUCER	GAS	DATE 7-16-24
------------------------	----------------------	------------------------	-----	-----	----------	-----	------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	960
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Exposed for
Water	Y/N	Y/N	Y/N	Y/N	Waterlogged & exposed

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BAT-OK

Well is NOT T/A'd

Signature:		OIL CONSERVATION DIVISION
Printed name:		Entered into RBDMS
Title:		Re-test
E-mail Address:		
Date:	Phone:	
Witness:	Larry Polson	

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 365770

CONDITIONS

Operator: EOR OPERATING COMPANY 4622 Maple Avenue Dallas, TX 75219	OGRID: 257420
	Action Number: 365770
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/3/2024