

District
1525 N. French Dr., Hobbs, NM 88240
Phone: (505) 393-6151 Fax: (505) 393-6720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name EOR	API Number 30-041-00137
Property Name M. Inesand	Well No. #195

1. Surface Location									
UL - Lot P	Section 13	Township 8S	Range 34E	Feet from	N/S Line	Feet from	E/W Line	County Rosv.	

2. Well Status									
TA'D WELL NO	YES	SHUT-IN NO	YES	INJ NO	INJECTOR	SWD	OIL	PRODUCER	GAS
									DATE 7-16-24

OBSERVED DATA

	(A) Surface	(B) Internl(1)	(C) Internl(2)	(D) Prod Csg	(E) Tubing
Pressure	0			50	520
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Delayed for
Water	Y/N	Y/N	Y/N	Y/N	Waterford Y
					apples

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Prod. Csg had slight fluid

Signature:		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date:	Phone:		
Witness:	Dan Palmer		

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 365764

CONDITIONS

Operator: EOR OPERATING COMPANY 4622 Maple Avenue Dallas, TX 75219	OGRID: 257420
	Action Number: 365764
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/3/2024