

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens & Johnson Operating Co.	API Number 30-015-02227
Property Name East Millman Pool Unit Tract 6	Well No 1

Surface Location									
U - Lot G	Section 13	Township 19S	Range 28E	Feet from 1980	N/S Line FWL	Feet From 1980	EW Line FEL	County Eddy	

Well Status					DATE
TA'D Well YES (NO)	SHUT-IN YES (NO)	INJECTOR (INJ)	PRODUCER OIL GAS		7/18/2024

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	800
Flow Characteristics					
Puff	Y/ (N)	Y/ N	Y/ N	Y/ (N)	CO2 —
Steady Flow	Y/ (N)	Y/ N	Y/ N	Y/ (N)	WTR —
Surges	Y/ (N)	Y/ N	Y/ N	Y/ (N)	GAS —
Down to nothing	(Y) N	Y/ N	Y/ N	(Y) N	If applicable type
Gas or Oil	Y/ (N)	Y/ N	Y/ N	Y/ (N)	fluid injected for
Water	Y/ (N)	Y/ N	Y/ N	Y/ (N)	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

Signature: Mark Hope		OIL CONSERVATION DIVISION	
Printed name Mark Hope		Entered RBDMS	
Title: Pumper		Re-test	
E-mail Address hope-mark53@yahoo.com			
Date: 7/18/2024	Phone 575-748-5629		
Witness Barbara Gabe			

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 366985

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 366985
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024