

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Stephens + Johnson Operating Co.		API Number 30-015-02245
Property Name East Millman Unit		Well No 143

Surface Location

U.L. - Lot K	Section 14	Township 19S	Range 28E	Feet from 1980	N/S Line FSL	Feet From 1980	EW Line FWL	County Eddy
------------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	-----------------------	-----------------------

Well Status

TA'D Well YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ SWD	PRODUCER OIL GAS	DATE 7/18/2024
--	--	--	---------------------	--------------------------

OBSERVED DATA

	(A) Surf-Interm.	(B) Interm. (1)	(C) Interm. (2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	900
Flow Characteristics					
Puff	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	CO2 <input type="checkbox"/>
Steady Flow	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y N	If applicable type
Gas or Oil	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	fluid injected for
Water	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Y/ <input checked="" type="radio"/> N	Waterflood

If Braden head flowed water, check all the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: Please state for each string (A, B, C, D, E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Mark Hope		OIL CONSERVATION DIVISION	
Printed name Mark Hope		Entered RBDMS	
Title: Pumper		Re-test	
E-mail Address hope-mark53@yahoo.com			
Date: 7/18/2024	Phone 575-748-5629		
	Witness Dan Howard		

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 367041

CONDITIONS

Operator: STEPHENS & JOHNSON OP CO P.O. Box 2249 Wichita Falls, TX 76307	OGRID: 19958
	Action Number: 367041
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024