

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name LH Operating, LLC		API Number 30.015-05364	
Property Name Skelly Unit		Well No. 47	

Surface Location									
UL - Lot E	Section 23	Township 17S	Range 31E	Feet from 1980	N/S Line N	Feet From 660	E/W Line W	County Eddy	

Well Status									
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 7/8/2024	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	0		0	700
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT.OIG-Well is shut in-replacing maining. line

Signature: Michael Burton		OIL CONSERVATION DIVISION	
Printed name: Mike Burton			
Title:			
E-mail Address: Mike@lhoperating.com			
Date: 7-8-24	Phone: 575-499-5306	Entered into RBDMS	
Witness: [Signature]		Re-test	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 366723

CONDITIONS

Operator: LH Operating, LLC 3730 Kirby Drive Houston, TX 77098	OGRID: 329319
	Action Number: 366723
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024