

State of New Mexico  
 Energy, Minerals and Natural Resources Department  
 Oil Conservation Division Artesia District Office

**BRADENHEAD TEST REPORT**

Operator Name <i>AD Operating</i>	API Number <i>30015-05421</i>
Property Name <i>Skelly Unit</i>	Well No. <i>86</i>

**1. Surface Location**

UL - Lot <i>C</i>	Section <i>27</i>	Township <i>17S</i>	Range <i>31E</i>	Feet from <i>660</i>	N/S Line <i>N</i>	Feet From <i>1900</i>	E/W Line <i>W</i>	County <i>Eddy</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	-----------------------

**Well Status**

TA'D WELL YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	SHUT-IN YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	INJECTOR INJ <input checked="" type="checkbox"/> SWD <input type="checkbox"/>	OIL PRODUCER OIL <input type="checkbox"/> GAS <input type="checkbox"/>	DATE <i>7/8/2024</i>
----------------------------------------------------------------------------------	--------------------------------------------------------------------------------	----------------------------------------------------------------------------------	---------------------------------------------------------------------------	-------------------------

**OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	<i>0</i>	<i>0</i>		<i>0</i>	<i>800</i>
Flow Characteristics					
Puff	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2 <input type="checkbox"/>
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR <input checked="" type="checkbox"/>
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS <input type="checkbox"/>
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Type of Fluid Injected for Waterflood if applies
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.  
*BHT-OK-Well is shut in. replacing main in line*

Signature: <i>Mike Burton</i>	OIL CONSERVATION DIVISION
Printed name: <i>Mike Burton</i>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: <i>7-8-24</i>	Phone:
Witness: <i>Barbara J. [Signature]</i>	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 366734

**CONDITIONS**

Operator: LH Operating, LLC 3730 Kirby Drive Houston, TX 77098	OGRID: 329319
	Action Number: 366734
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

**CONDITIONS**

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024