

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name <i>NO Operating</i>	API Number <i>30-015-05432</i>
Property Name <i>Skelly Unit</i>	Well No. <i>84</i>

7. Surface Location

UL - Lot <i>A</i>	Section <i>27</i>	Township <i>17S</i>	Range <i>31E</i>	Feet from <i>460</i>	N/S Line <i>N</i>	Feet From <i>460</i>	E/W Line <i>E</i>	County <i>Eddy</i>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-----------------------

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	OIL	PRODUCER	GAS	DATE <i>7/8/2024</i>
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----	----------	-----	-------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Cng	(E) Tubing
Pressure	<i>5</i>			<i>0</i>	<i>100</i>
Flow Characteristics					
Puff	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	CO2
Steady Flow	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	WTR. ☒
Surges	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	GAS
Down to nothing	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Type of Fluid
Gas or Oil	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Injected for
Water	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	<i>Y/N</i>	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-DIC - Well shut in replacing main line

Signature: <i>M. Ke Burton</i>	OIL CONSERVATION DIVISION
Printed name: <i>M. Ke Burton</i>	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: <i>7-8-24</i>	Phone:
Witness: <i>Rabun Lopez</i>	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 366731

CONDITIONS

Operator: LH Operating, LLC 3730 Kirby Drive Houston, TX 77098	OGRID: 329319
	Action Number: 366731
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024