

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

Operator Name Chi Operating	API Number 30-015-35791
Property Name Benson Delaware Unit	Well No. 12

2. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
E	12	19S	30E	2547	N	519	W	Eddy

Well Status

YES	TA'D WELL	YES	SHUT-IN	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
	(NO)		(NO)	(INJ)						7/18/2024

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0			0	800
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS
Down to nothing	(Y) N	Y / N	Y / N	(Y) / N	Type of fluid injected for
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	Waterflood if applies
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT.OIL

Signature: J L Duran	OIL CONSERVATION DIVISION
Printed name: Robert Thomas Duran	Entered into RBDMS
Title: Prod op	Re-test
E-mail Address: atom17@me.com	
Date: 7-18-24	
Phone: 505 706-5028	
Witness: [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 367698

CONDITIONS

Operator: CHI OPERATING INC P.O. Box 1799 Midland, TX 79702	OGRID: 4378
	Action Number: 367698
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024