

Southern District
1625 N. French Dr, Hobbs, NM 88240
Phone: (575) 241-7063

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name DKL Field Services LLC	API Number 30-025-44144
Property Name Doodle Bug State SWP #001	Well No. #001

1. Surface Location

UL - Lot 6	Section 16	Township 22S	Range 33E	Feet from 1498	N/S Line FNL	Feet From 2396	E/W Line FEL	County Log
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

TA'D WELL YES NO	SHUT-IN YES NO	INJ NO	INJECTOR SWD	OIL NO	PRODUCER NO	GAS NO	DATE 7-28-2024
----------------------------	--------------------------	------------------	------------------------	------------------	-----------------------	------------------	--------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	50	0	NA	50	1612
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input checked="" type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Casing down to 0 in 5 sec

Signature: Kerry Mackey	OIL CONSERVATION DIVISION
Printed name: Kerry Mackey	Entered into RBDMS
Title: Manager	Re-test
E-mail Address: Kerry.Mackey@delteklogistics.com	GR
Date: 7-28-2024	
Phone: 575-631-8198	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 371225

CONDITIONS

Operator: DKL Field Services, LLC 310 Seven Springs Way Brentwood, TN 37027	OGRID: 372603
	Action Number: 371225
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/4/2024