District 2-Artesia

State of New Mexico Minerals and Natural Resources Denau

Energy, Minerals and Natural Resources Department Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT ² Surface Location Setting 53

TA'D WELL 8 SHY NFTURS NO O Z Status Well Status INJECTOR SWD OIL GAS

OBSERVED DATA

Water	Gas or Oil	Down to nothing	Surges	Steady Flow	Puff	Flow Characteristics	Pressure	<u> </u>
N) A	(N) A	(Y) Z	A / A	Y/@	(3) N		0	(A)Surface
N / A	N / N	N / N	N A	KIA	NIA			(B)Interm(1)
N / A	N / N	7 · Z	Y Z	N/A	Y / Y			(C)(b)(c)(2)
N/A	W/A	NA	A/A	W) Y	YY N		0	(D)Prod Cang
	Apples.	lajered for	GAS	WTR	COZ		TA	(E)Tubing

Remarks - Please state for each string (A.B.C.D.E) pertinent information regarding bleed down or continuous build up if applies. A Status BHT

Dale: Tide Signature: E-mail Address: Printed name: Witness Re-test Entered into RBDMS OIL CONSERVATION DIVISION

INSTRUCTIONS ON BACK OF THIS FORM

Released to Imaging: 12/5/2024 3:27:33 PM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 375782

CONDITIONS

Operator:	OGRID:
Extex Operating Company	330423
1616 S. Voss Road	Action Number:
Houston, TX 77057	375782
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Crea	ated By		Condition Date
tim	othy.martin	None	12/5/2024