

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office
BRADENHEAD TEST REPORT

Operator Name San Mateo Stebbins	API Number 30-015-45535
Property Name Shinnery Oak SWD	Well No. 3

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
E	2	215	28E	3333	S	1015	W	Edcity

Well Status

TA'D WELL	SHUT-IN	INJ	INJECTOR	OIL	PRODUCER	GAS	DATE
YES ☐ NO ☒	NO ☐ YES ☒	NO ☐ INJ ☐	SWD ☒	OIL ☐	PRODUCER ☐	GAS ☐	7/10/2024 ✓

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0		0	1600
<u>Flow Characteristics</u>					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ✓
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Detected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT. OK

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: Barbara [Signature]	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 372337

CONDITIONS

Operator: San Mateo Stebbins Water Management, LLC 5400 LBJ Freeway Dallas, TX 75240	OGRID: 328762
	Action Number: 372337
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/5/2024