Southern District 1625 N French Dr, Hobbs, NM 88240 Phone: (575) 241-7063

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Property Name 1. Surface Location 1. Surface Location 1. Section Township Range Feet from N/S Line Feet From E/N	Well No. 141 W Line County Lee 7. 8- 24
Value Valu	DATE 7.8-24
Vel Status Vel Status Ves Shut-in No INJECTOR SWD OIL PRODUCER GAS	DATE 7.8-24
Vel Status	DATE 7.8-24
YES	7.8-24
YES NO YES NO IND SWD OIL GAS	7.8-24
(A)Surface (B)Interm(1) (C)Interm(2) (D)Prod Csng	(E)Tubing
Pressure O Flow Characteristics Y / N	(E)Tubing
Flow Characteristics	And the second s
Flow Characteristics	210
Steady Flow Y / N Y / N Y / N Y / N Surges Y / N Y / N Y / N Y / N Down to nothing Down to nothing Y / N Y / N Y / N Y / N Gas or Oil Y / N Y / N Y / N Y / N Y / N Water Y / N Y / N Y / N Y / N Y / N	
Surges Y / N Y / N Y / N Down to nothing (D) / N Y / N	N CO2 WTR
Down to nothing O/N Gas or Oil Water Y/N Y/N Y/N Y/N Y/N Y/N Y/N Y/	GAS
Gas or Oil Y/N Y/N Y/N Y/N Y/N Y/O	Type of Fluid
Water Y/N Y/N Y/O	Waterflood if
Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.	Y
Signature: OIL CONSERVATION D	
Printed name: DANA GINANNI Entered into RBDMS	
Title:	
E-mail Address: dence rhombusup, com Date: 7.8-24 Phone: 5354416302	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 372388

CONDITIONS

Operator:	OGRID:
RHOMBUS OPERATING CO LTD	19111
P.O Box 18979	Action Number:
Golden, CO 80402	372388
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
timothy.martin	None	12/5/2024