District I 1625 N French Dr., Hobbs, NM 88240 Phone (575) 393-6161 Fax, 1575) 393-0120

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT Operator Name MORNINGSTAR OPERATING LLC Property Name VACUUM GRAYBURG SAN ANDRES UNIT					3(API Number 30-025-02264		
						Well No. 039		
	7	Granda and and and and and and and and and		1. Surface Locat	ion			
UL-Lor H	Section 2	Township 18S	Rauge 34E	Feet from 1980	N/S Line FNL	Feet From 660	EAV Line FEL	LEA
				Well Statu	\$	A TOTAL PROPERTY OF THE PARTY O		
TA'D ES	WELL	O YES	SHUT-IN	INJECTOR		PRODUCER		DATE

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	8			J'h	
Flow Characteristics				70	120
Puff	Y/(N)	TYIN	VIN	Y/N	CO2
Steady Flow	Y/N	N 1 N	AVA	YIN	WTR_
Surges	YIN	NYY	Y/N	Y/N	GAS
Down to nothing	N	Y/N	YIN	Y/N	Type of Fleid Injected for
Gas or Oil	Y // N	YIN	Y/N	Y/N	Waterflood if
Water	Y/N	YIN	Y/N	YIN	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

name Yore Water	OIL CONSERVATION DIVISION	
nted name. TOLL Must	Control of the second s	
TOO [MARK!	Entered into RBDMS //	
ille Obe Oppration	Entered into RBDMS Re-test	

INSTRUCTIONS ON BACK OF THIS FORM

482 352 4942

Phone

Witness

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 385083

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	385083
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortr	er None	12/9/2024