District 1
1625 N French Dr , Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office
BRADENHEAD TEST REPORT

Operator Name	API Number
MORNINGSTAR OPERATING LLC	30-025-02274

Property Name	Well No.
VACUUM GRAYBURG SAN ANDRES UNIT	009

¹· Surface Location

Ul. - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
P	2	18S	34E		660	FSL	660	FEL	LEA

Well Status

TA'D WELL		SHUT-IN		INJECTOR		PRODUCER		DATE
YES (NO) (YES)		NO	INJ	SWD	(OIL)	GAS		6-29-24

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	0			60	240
Flow Characteristics					
Puff	Y /(N)	Y / N	Y / N	Y / N	CO2
Steady Flow	Y /(N)	Y / N	Y / N	Y / N	WTR ___
Surges	Y /(N)	Y / N	Y / N	Y / N	GAS ___
Down to nothing	(Y) N	Y / N	Y / N	Y / N	Type of Field Injected for
Gas or Oil	Y /(N)	Y / N	Y / N	Y / N	Waterflood if applies
Water	Y /(N)	Y / N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Hole in tubing

Signature: Jose Mata	OIL CONSERVATION DIVISION	
Printed name: Jose Mata	Entered into RBDMS	
Title: Lease Operator	Re-test	
E-mail Address: JM @ crfieldsvcs.com		
Date: 6-29-24 Phone: 1082 352 4942		
Witness		

INSTRUCTIONS ON BACK OF THIS FORM

CONDITIONS

Action 385016

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	330132
	Action Number: 385016
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/9/2024