

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Artesia District Office

**BRADENHEAD TEST REPORT**

Operator Name <b>Roughhouse Operating</b>		API Number <b>30.015-00179</b>
Property Name <b>Atoka San Andres</b>		Well No. <b>123</b>

**1. Surface Location**

DB - Lot <b>P</b>	Section <b>11</b>	Township <b>18S</b>	Range <b>26E</b>	Feet from <b>660</b>	N/S Line <b>S</b>	Feet From <b>660</b>	E/W Line <b>E</b>	County <b>Eddy</b>
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	-------------------------	----------------------	-----------------------

**Well Status**

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ	SWD	OIL	PRODUCER GAS	DATE <b>9/18/2024</b>
--	--	--	-----	-----	-----------------	--------------------------

**OBSERVED DATA**

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	<input type="radio"/>	<input type="radio"/>		<input type="radio"/>	<input type="radio"/>
Flow Characteristics					
Puff	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	CO2
Steady Flow	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	WTR <input checked="" type="checkbox"/>
Surges	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	GAS <input type="checkbox"/>
Down to nothing	<input checked="" type="radio"/> Y / N	<input checked="" type="radio"/> Y / N	Y / N	<input checked="" type="radio"/> Y / N	Type of fluid injected for water flood if applies
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	
Water	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / <input checked="" type="radio"/> N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

**BHT-OK**

Signature: <b>DeLinda Little</b>	OIL CONSERVATION DIVISION
Printed name: <b>DeLinda Little</b>	Entered into RBDMS
Title:	Re-test
E-mail Address: <b>dlittle@oilconservation.com</b>	
Date:	
Phone:	
Witness: <b>Barbara Little</b>	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 386256

CONDITIONS

Operator: Roughhouse Operating, LLC 16051 Addison Road Addison, TX 75001	OGRID: 330608
	Action Number: 386256
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024