

District 2-Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Artesia District Office

BRADENHEAD TEST REPORT

| | |
|---|-----------------------------------|
| Operator Name Roughhouse Operating | API Number 30-015-00293 |
| Property Name Atola San Andres Unit | Well No. 128 |

1. Surface Location

| | | | | | | | | |
|--------------------|----------------------|------------------------|---------------------|-------------------------|----------------------|--------------------------|----------------------|-----------------------|
| UL Lot 3 | Section 13 | Township 18S | Range 26E | Feet from 330 | N/S Line N | Feet From 2310 | E/W Line E | County Eddy |
|--------------------|----------------------|------------------------|---------------------|-------------------------|----------------------|--------------------------|----------------------|-----------------------|

Well Status

| | | | | | | | | | | |
|-----|------------------------|-----|----------------------|------------|----------|-----|-----|----------|-----|--------------------------|
| YES | TA'D WELL NO | YES | SHUT-IN NO | INJ | INJECTOR | SWD | OIL | PRODUCER | GAS | DATE 9/18/2024 |
|-----|------------------------|-----|----------------------|------------|----------|-----|-----|----------|-----|--------------------------|

OBSERVED DATA

| | (A) Surface | (B) Interm(1) | (C) Interm(2) | (D) Prod Csg | (E) Tubing |
|----------------------|-------------|---------------|---------------|--------------|---|
| Pressure | 0 | 0 | / | 0 | 25 |
| Flow Characteristics | | | | | |
| Puff | Y / N | Y / N | Y / N | Y / N | CO2 |
| Steady Flow | Y / N | Y / N | Y / N | Y / N | WTR <input checked="" type="checkbox"/> |
| Surges | Y / N | Y / N | Y / N | Y / N | GAS <input type="checkbox"/> |
| Down to nothing | Y / N | Y / N | Y / N | Y / N | Type of fluid |
| Gas or Oil | Y / N | Y / N | Y / N | Y / N | Injected for |
| Water | Y / N | Y / N | Y / N | Y / N | Waterflood if |
| | | | | | applies |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

| | |
|--|---------------------------|
| Signature: Delinda Little | OIL CONSERVATION DIVISION |
| Printed name: Delinda Little | Entered into RBDMS |
| Title: | Re-test |
| E-mail Address: dlittle@rolfsun oil.com | |
| Date: | |
| Phone: | |
| Witness: Barbara J. Schick | |

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 386243

CONDITIONS

| | |
|---|--|
| Operator: Roughhouse Operating, LLC 16051 Addison Road Addison, TX 75001 | OGRID: 330608 |
| | Action Number: 386243 |
| | Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| kfortner | None | 12/10/2024 |