

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Benton Crude Oil LLC	API Number 30-025-11422
Property Name Hemphrey Queen	Well ID 002

Surface Location									
District D	Section 3	Township 25 S	Range 37 E	Feet from 330	N/S Line N	Feet from 990	EPW Line W	County LEA	

Well Status									
Is a TD Well? NO	Is it a Shut-in? NO	Is it an Injector? NO	Is it a SWD? NO	Is it an Oil Producer? NO	Is it a Gas Producer? NO	DATE 9-18-24			

OBSERVED DATA

	(A) Surface	(B) Int (cm1)	(C) Int (cm2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	50
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ✓
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Flow
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Wetness
Water	Y / N	Y / N	Y / N	Y / N	Waterhead

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding flow, down or continuous build up if applies.

Signature 	Oil Conservation Division Entered into RBOMS Re-test
Printed name Gary Robinson	
Title	
Business Address	
Date	
Phone	
Address	

INSTRUCTIONS: DO NOT WRITE INTO SPACES

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 386002

CONDITIONS

Operator: Benton Crude Oil LLC 2201 Menaul Blvd NE Ste A Albuquerque, NM 87107	OGRID: 331974
	Action Number: 386002
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024