

Form 10-1
10-25-2019, REV. 10-1-2019
Printed on Recycled Paper

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Benton Crude Oil LLC	AOI Number 30-025-11426
Property Name Humphrey Queen	Well ID 017

Surface Location									
UTM Zone J	Section 3	Township 25 S	Range 37 E	Feet from 2310	N/S Line S	Feet from 1650	E/W Line E	County Lea	

Well Status									
PROD WELL ☐ YES ☒ NO	SHUT-IN ☐ YES ☒ NO	INJECTOR ☒ YES ☐ NO	SWD ☐ YES ☐ NO	OIL ☐ YES ☐ NO	PRODUCER ☐ YES ☐ NO	GAS ☐ YES ☐ NO	DATE 9/18/24		

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod. Casing	(E) Tubing
Pressure	0			0	VAC
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WIR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Disposal
Water	Y/N	Y/N	Y/N	Y/N	Waterhead & spuds

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature	OIL CONSERVATION DIVISION
Printed name	Entered into RBDMS
Title	Re-test
E-mail Address	
Date	
Phone	
Address	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 386004

CONDITIONS

Operator: Benton Crude Oil LLC 2201 Menaul Blvd NE Ste A Albuquerque, NM 87107	OGRID: 331974
	Action Number: 386004
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024