

Revised 10/1/2019
 OCS Form 001-01-01
 Oil Conservation Division

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division, Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Benton Crude Oil LLC	API Number 30-025-23186
Property Name Langlie Mattix Queen	Well Number 022

Surface Location									
U-T/L	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County	
W	15	25 S	37 E	668	S	1633	W	LFA	

Well Status											
Y/TD Well	NO	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
											9-18-24

OBSERVED DATA

	(A) Surface	(B) Bottom	(C) Interval	(D) Prod. Casing	(E) Tubing
Pressure	0			0	100
Flow Characteristics					
Puff	Y	Y/N	Y/N	Y	CO2
Steady Flow	Y	Y/N	Y/N	Y	W. H. ✓
Surges	Y	Y/N	Y/N	Y	GAS
Down to nothing	Y	Y/N	Y/N	Y	Type of fluid
Gas or Oil	Y	Y/N	Y/N	Y	Exposed to
Water	Y	Y/N	Y/N	Y	Watermark if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding life at down or continuous build up if applies.

Signature	OIL CONSERVATION DIVISION Entered into RBOMS Re-test 
Printed name	
Title	
E-mail Address	
Date	
Place	
Printed name	

INTERPRETATIONS OF DATA OF THIS TEST

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 385998

CONDITIONS

Operator: Benton Crude Oil LLC 2201 Menaul Blvd NE Ste A Albuquerque, NM 87107	OGRID: 331974
	Action Number: 385998
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024