

Form 10-100
 10/23/2019 Edition
 Produced by N.M.

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Benton Crude Oil LLC	API Number 30-025-11607
Property Name Langlie Matrix Queen	011

Surface Location					
UL Lot D	Section 15	Township 25 S	Range 37 E	Feet from 1400	N/S Line N
				Feet from 1980	E/W Line E
					County LEA

Well Status					
TAB WELL NO	YES	SHUT-IN NO	INJ NO	PRODUCER NO	DATE 9-18-24

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod. Casing	(E) Tubing
Pressure	0			0	50
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO ₂
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of flow
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature Dany Pedraza	OIL CONSERVATION DIVISION Entered into RBDMS Re-test 
Printed name Dany Pedraza	
Title Field Engineer	
Business Address 1000 N. Main St.	
Home 505-234-1234	
Phone 505-234-1234	
Work 505-234-1234	

INTRODUCTION OF BALD OF RBDMS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 385986

CONDITIONS

Operator: Benton Crude Oil LLC 2201 Menaul Blvd NE Ste A Albuquerque, NM 87107	OGRID: 331974
	Action Number: 385986
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024