

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0320

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-20143
Property Name VACUUM GLORIETA WEST UNIT		Well No 034

1. Surface Location									
UL - Lot K	Section 25	Township 17S	Range 34E	Feet from 1650	N/S Line FSL	Feet From 1650	E/W Line FWL	County LEA	

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ NO	INJECTOR NO	SWD NO	PRODUCER YES	GAS NO	DATE 7-29-2024

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	N/A	N/A	30	240
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 WTR GAS Type of fluid Injected for Waterflood if applicable
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 		OIL CONSERVATION DIVISION	
Printed name: Jesus Romero		Entered into RBDMS	
Title: Field Specialist		Re-test	
E-mail Address: romero@cpind.com			
Date: 7-24-2024	Phone: 682-352-9714		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 388506

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 388506
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024